

McLeod Racing		
Service Code	Description	Price
RL1001	Replace Bearing on Collar	\$ 25.00
RL1300	Rebuild 1300 Series Hydraulic Bearing	\$ 50.00
RL1400	Rebuild 1400 Series Hydraulic Bearing	\$ 50.00
RL2001	Rebuild 100 Disc Series	\$ 60.00
RL2002	Rebuild 200 Disc Series	\$ 60.00
RL2003	Rebuild 300 Disc Series	\$ 60.00
RL2004	Rebuild 400 Disc Series	\$ 120.00
RL2005	Rebuild 500 Disc Series	\$ 100.00
RL2006	Rebuild 600 Disc Series	\$ 120.00
RL2007	Rebuild 700 Disc Series	\$ 60.00
RL2008	Rebuild 800 Disc Series	\$ 80.00
RL2010	Surface Grind Iron Disc	\$ 50.00
RL2011	Replace Sold Hub – Single	\$ 35.00
RL2012	Replace Sold Hub – Pair	\$ 100.00
RL2014	SFI Certification – Disc – McLeod Product Only	\$ 30.00
RL2016	Replace Sprung Hub	\$ 75.00
RL3001	Rebuild Pressure Place, Except Diaphragm 8.0 Mag Force	\$ 90.00
RL3002	Replace Non Billet Levers (Most Styles) All 3.0 Except Soft Lok	\$ 60.00
RL3003	Replace Soft Lok Levers (Gold) All 3.0	\$ 150.00
RL3003-1	Replace Billet Levers (Except Gold) 3.0	\$ 120.00
RL3004	Replace Steel Heat Shield Each	\$ 125.00
RL3005	Replace Bronze Heat Shield	\$ 250.00
RL3006	Cut & Drill Install Steel Heat Shield	\$ 160.00
RL3007	Cut & Drill Install Bronze Heat Shield	\$ 200.00
RL3008	Cut & Drill Install Casting for Bronze Heat Shield	\$ 100.00
RL3009	Blanchard Grind Casting, Replace Old Heat Shield	\$ 150.00
RL3010	Rebuild Pressure Plate w/ Steel Heat Shield Alum or Ductile	\$ 200.00
RL3011	Rebuild Pressure Plate w/ Bronze Heat Shield	\$ 350.00
RL3012	Change Pressure Plate, Non Adjustable	\$ 65.00
RL3012-1	Change Pressure Plate, Adjustable	\$ 75.00
RL3013	SFI Certification – Pressure Plate	\$ 30.00
RL3014	Replace Diaphragm Spring Only	\$ 75.00
RL3016	Convert 360530 into 360535 & Rebuild	\$ 300.00
RL3017	Convert 360530 into 360536 & Rebuild	\$ 350.00
RL3018	Replace Borg & Beck Long Cover	\$ 65.00
RL3019	Replace Borg & Beck Long Welded Cover	\$ 100.00
RL3020	Replace Thick Long Cover	\$ 75.00
RL3021	Replace Long Cover Short Cups, 360530, 360420, 360532	\$ 100.00
RL30222	Replace Adjustable Pressure Plate Long Cover	\$ 150.00

RL3025	Rebuild, New Alum. Pressure Plate Ring w/ Steel Heat Shield	\$ 300.00
RL3026	Rebuild, New Alum. Pressure Place Ring w/ Bronze Heat Shield	\$ 375.00
RL3028	Convert Pressure Plate to 13 Turn Adjustable	\$ 250.00
RL3029	Service, Soft Lok Tune UP, Clean, Blast and Lube	\$ 100.00
RL3030	Convert 360540 to 360550	\$ 300.00
RL4001	Resurface Flywheel	\$ 35.00
RL4001-S	Resurface Flywheel w/ Studs	\$ 55.00
RL4005	SFI Certification – Flywheel	\$ 30.00
RL4010	Install Flywheel Studs	\$ 75.00
RL4011	Replace Steel Flywheel Ring Gear	\$ 50.00
RL4012	Replace Alum. Flywheel Ring Gear	\$ 75.00
RL6001	Glass bead Floater, Each	\$ 20.00
RL6002	Blanchard Grind Floater	\$ 50.00
RL6002-S	Blanchard Grind Strapped Floater	\$ 75.00
RL6005	Replace Spring Oval Track Single Spring	\$ 60.00
RL6007	Replace 8.0 Heat Shield (Flywheel or Pressure Plate)	\$ 125.00
RL6300	Rebuild Alum Street Twin Push Type	\$ 525.00
RL6322	Rebuild Alum Street Twin Pull Type	\$ 525.00
RL6400	Rebuild Steel Street Twin Push Type	\$ 500.00
RL6422	Rebuild Steel Street Twin Pull Type	\$ 450.00
RL6552	Rebuild 4700 Series Tractor Pull	\$ 950.00
RL6561	Rebuild Complete Mag Force Twin	\$ 550.00
RL6562	Rebuild Complete Mag Force Triple	\$ 750.00
RL6564	Convert Pin Drive Unit to Strapped Drive	\$ 150.00
RL6565	Rebuild Complete Soft Lok	\$ 550.00
RL6566	Rebuild Complete RST w/ Organic Disc	\$ 400.00
RL6566-1	Rebuild Complete RST w/ Kevlar Disc	\$ 450.00
RL6567	Rebuild Complete RXT w/ Ceramic Disc	\$ 540.00
RL6568	Balance Multi Disc Unit as Assembly	\$ 125.00
RL6569	SFI Certification – Bellhousing	\$ 30.00